

臨時封閉百和路南行**Temporary Closure of Pak Wo Road southbound**

為配合位於百和路南行的電感探測線圈建造工程，一段介乎連接粉嶺公路南行的支路與興興路的百和路南行將於 2020 年 9 月 19 日及 23 日凌晨零時 30 分至上午 5 時 30 分臨時封閉。沿馬會道南行前往和合石/粉嶺的車輛，須改經支路、粉嶺公路南行、林錦公路交匯處、粉嶺公路北行及支路(出口 7B)。

有關地點將會設置適當臨時交通輔助設施，駕駛人士請遵照指示，並小心駕駛。

有關臨時封閉道路詳情如下：


2020 年 9 月 19 日及 23 日凌晨零時 30 分至上午 5 時 30 分

To facilitate the construction of loop detector at Pak Wo Road southbound, a section of Pak Wo Road southbound between the slip road leading to Fanling Highway southbound and Wo Hing Road will be temporarily closed from 00:30 am to 05:30 am on 19 & 23 September 2020. During the road closure period, the affected vehicles on Jockey Club Road southbound heading for Wo Hop Shek/Fanling will be diverted via slip road, Fanling Highway southbound, Lam Kam Road Interchange, Fanling Highway northbound, the slip road (Exit 7B).

Appropriate traffic aids will be erected on site. Motorists are advised to follow the instructions on site and drive in utmost care.

Please see below details the temporary road closure:

00:30 a.m. to 05:30 a.m. on 19 & 23 September 2020



路政署將密切留意交通情況並採取必要措施，務求將交通影響減至最低。如對上述交通安排有任何查詢，請致電二十四小時熱線：8208 2230。

Highways Department will closely monitor the traffic conditions and implement any necessary measures to ensure the traffic impacts are kept to a minimum. Should you have any enquiries, please call the 24-hour hotline: 8208 2230.