

臨時封閉粉嶺公路北行連接百和路的支路(出口 7B)**Temporary Closure of Slip Road Leading from Fanling Highway northbound to Pak Wo Road (EXIT 7B)**

為配合粉嶺公路北行和合石段的路面重新定綫工程，沿粉嶺公路北行連接百和路的支路(出口 7B)，將於 2019 年 2 月 24 日凌晨零時 01 分至上午 6 時臨時封閉。在道路封閉期間，沿粉嶺公路北行前往百和路南行的車輛，將改經出口 7C、百和路北行、馬會道北行、沙頭角路-龍躍頭迴旋處、馬會道南行及百和路南行。有關地點將會設置適當臨時交通輔助設施，駕駛人士請遵照現場指示，並小心駕駛。

有關臨時封閉道路詳情如下：


2019 年 2 月 24 日凌晨零時 01 分至上午 6 時

To facilitate the road re-alignment works on Fanling Highway northbound at Wo Hop Shek, the slip road from Fanling Highway northbound leading to Pak Wo Road (Exit 7B) will be temporarily closed from 00:01 a.m. to 06:00 a.m. on 24 February 2019.

During the road closure period, the affected vehicles on Fanling Highway northbound heading for Pak Wo Road southbound will be diverted via slip road (Exit 7C), Pak Wo Road northbound, Jockey Club Road northbound, Sha Tau Kok Road—Lung Yuek Tau roundabout, Jockey Club Road southbound and Pak Wo Road southbound. Appropriate traffic aids will be erected on site. Motorists are advised to follow the instructions on site and drive in utmost care.

Please see below details the temporary road closure:

00:01 a.m. to 06:00 a.m. on 24 February 2019



路政署將密切留意交通情況並採取必要措施，務求將交通影響減至最低。如對上述交通安排有任何查詢，請致電二十四小時熱線：8208 2230。

Highways Department will closely monitor the traffic conditions and implement any necessary measures to ensure the traffic impacts are kept to a minimum. Should you have any enquiries, please call the 24-hour hotline: 8208 2230.